


SPECIAL AIRWORTHINESS INFORMATION BULLETIN

Aircraft Certification Service
Washington, DC



U.S. Department
of Transportation

**Federal Aviation
Administration**

No. CE-03-01
October 8, 2002

We post SAIBs on the internet at "av-info.faa.gov"

This is information only. Recommendations are not mandatory.

Introduction

This Special Airworthiness Information Bulletin (SAIB) advises you, owners and operators of SOCATA TBM 700 airplanes, of issuance of Anjou Aeronautique Service Bulletin (SB) 343-1-25-01.

Background

The FAA conducted a review of Anjou Aeronautique Service Bulletin (SB) 343-1-25-01 that applies to certain seat belts installed in the SOCATA TBM 700. The DGAC of France, after reviewing the seat belt and its design, issued a French AD to address the situation identified in the service bulletin. After concluding our evaluation of the safety recommendation, we have decided that an Airworthiness Directive is not appropriate at this time.

Owners and operators of SOCATA TBM 700 airplanes should also note that there have been Airworthiness Directives issued against these airplanes concerning other safety issues.

Recommendations

The service bulletin identified in this document is not considered appropriate for AD action at this time; however, the FAA strongly suggests that all owners and operators of the SOCATA TBM 700 airplanes review their compliance with the service bulletin listed below.

Anjou Aeronautique Service Bulletin Number	MODEL	DATE	TITLE
343-1-25-01	Seat belts of applicable model number installed in: SOCATA TBM 700	October 23, 2001	Safety Belts and Restraint Systems Type 343-1

The Service Bulletin Can Be Obtained From:

SOCATA Aircraft, Groupe Aerospatiale, North Perry Airport, 7501 Pembroke Road, Pembroke Pines, FL 33023; 954-893-1400 phone; 954-964-4141 facsimile

or:

Anjou Aeronautique, 13 Avenue De L'osier, 49125 Tierce, France; 011-33-241-42-88-92 phone; 011-33-241-42-15-77 facsimile

For Further Information Contact

Karl M. Schletzbaum, Aerospace Engineer, FAA, Project Support Branch (ACE-112), Small Airplane Directorate, 901 Locust Street, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090; email: karl.schletzbaum@faa.gov